

Supplemental Form PTO-1449 Modified			Docket No.: 52275-00005USPX	Serial No.: not assigned		
List of Patents and Publications Cited by Applicant (Use several sheets if necessary)			Applicants: Joachim SACHS et al.	U.S. RT JC986 U.S. 09/89427 06/28/01		
U.S. Patent Department of Commerce Patent and Trademark Office			Filing Date: herewith	Group: not assigned		
U.S. PATENT DOCUMENTS						
Examiner Initial		Document No.	Date	Name	Class	Subclass
<i>CJD</i>	A-1	5,243,595	Sep. 7, 1993	Woest et al.	370	85.13
FOREIGN PATENT DOCUMENTS						
Examiner Initial		Document No.	Date	Country	Translation	
					Yes	No
	B-1					
OTHER DOCUMENTS						
Examiner Initials		Author, Title, Date, Pertinent Pages, Etc.				
<i>CJD</i>	C-1	Kalabic, F., European Search Report, App. No. EP 00114344, Jan. 8, 2001, pp. 1-3				
<i>CJD</i>	C-2	Zhang, L., "Why TCP Timers Don't Work Well," Aug. 1986, Computer Communication Review, US, Association for computing Machinery, New York, Vol. 16, No. 3, pp. 397-405				
<i>CJD</i>	C-3	ETSI TS 125 301, V3.5.0 (2000-6), "Radio Interface Protocol Architecture," <u>Online!</u> , Mar. 1997, pp. 1-44; Internet: http://www.etsi.org				
<i>CJD</i>	C-4	Averbuch, R., et al., "Dynamic Adaptive Layer 2 Timer Adjustment," Mar. 1997, Motorola Technical Developments, US, Motorola, Inc., Schaumburg, Illinois, pp. 21-22				
<i>CJD</i>	C-5	Abbott, M. B., et al., "Increasing Network Throughput by Integrating Protocol Layers," Oct. 1993, IEEE/ACM Transactions on Networking, US, IEEE, Inc., New York, Vol. 1, No. 5, pp. 600-610				
<i>CJD</i>	C-6	3G TS25.303, v3.3.0 (2000-03), "Interlayer Procedures in Connected Mode," (Release 1999), 3 rd Generation Partnership Project, pp. 1-75				
<i>CJD</i>	C-7	3G TS 25.321, v3.3.0 (2000-3), "MAC Protocol Specification," (Release 1999), 3 rd Generation Partnership Project, pp. 39				
Date Examined:		12/20/04	Examiner:	<i>Cynthia Z. Dow</i>		